



SMUTE is mux'd w/ spare S4 using COL0
 COL0 = 0, SMUTES4 (PB6) = spare S4
 COL0 = 1, SMUTES4 (PB6) = SMUTE

R46-C72 are for EL DC-DC converter.
 For LED-BL, R46 - BLM31KN471SN1L, and C72 - 101R15N01J1V4T

REV: mod instruction: cut trace at U2-5 pad
 Bridge U2-5 to U2-7 with an 0805, 150K resistor.

BlueTooth I/O (data only, UART0)

IC-900 RCU MCU Clone		
Site	Number	Revision
C	1312B-KEOFF-001	A
Date:	8/04/2021	Sheet of
File:	C:\Users\...RDU_Clone_SchDoc	1
	Drawn By:	KEOFF